




Fasten wires, i

Using band, fasten throttle wire on upper side of frame, and fasten wire harness, clutch wire, high tension wire R on right side.





Pass throttle wire over tank fitting bracket, and pass clutch wire and wire harness R under the bracket.

After connecting wire harnesses R and L, clamp.

Fasten throttle wire and lead wires, using band.

Using band, fasten throttle wire on upper side (Orange) of frame, and fasten wire harness, clutch wire, high tension wire R on right side.

o of

Fasten generator cord with band.
Switch
High tension wire harness.



(Red/White)

Horn
Ignition coil
Ground (black)

Protector
Pass through holder.
Brake hose 2
Tachometer cable

Clamp.

Fasten generator cord with band.

Clamp

(+) cord to starting motor